



Bespoke Boot Measurement Guide

A. Leg length

Taken from the ground to immediatley below the small bone located on the outside of the leg just below the knee. Use a ridgid ruler if available and mark the leg with a marker.

B. Top of leg

Measure around the leg at the point where you have marked the leg for the boot length.

C. Calf measurement

Slide the tape around the leg to find the widest point of the calf. Mark the leg again at this point.

D. Height of calf

Measure from the ground to the widest point of the calf that you have just measured.

E. Lower leg

10" (25cm) from the floor, measure around the leg at this point.

F. Ankle area

6" (15cm) from the floor measure around the leg at this point. G. Ankle to lower leg

8" inches from the floor, measure around the leg at this point. H. Lower leg to calf 12" inches from the floor, measure around the leg at this point.

Top of calf to top of leg - measure 2" down from the measurement you took at the top of the leg.

J.

Foot Size (and Country eg UK, American)